

Suzanne Steab - July 2010 Inspection Report

From:

Karl Houskeeper

To:

kit@emerytelcom.net

Date:

7/29/2010 1:17 PM

Subject:

July 2010 Inspection Report

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: Horizon July 2010.pdf

Kit,

Attached is the July 2010 inspection report for Horizon.

Thanks,

Karl



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representatives Present During the Inspection:					
Company	Kit Pappas				
OGM	Karl Houskeeper				

Inspection Report

Permit Number:	C0070020
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, July 28, 2010
Start Date/Time:	7/28/2010 9:30:00 AM
End Date/Time:	7/28/2010 12:30:00 PM
Last Inspection:	Thursday, June 10, 2010

Inspector: Karl Houskeeper, Weather: Clear, Temp. 79 Deg. F. InspectionID Report Number: 2441

> Accepted by: jhelfric 7/29/2010

Permitee: HIDDEN SPLENDOR RESOURCES Operator: HIDDEN SPLENDOR RESOURCES

Site: HORIZON MINE

Address: .

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

1,577.00	Total Permitted
9.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Min	eral	Own	ere	hin

Types of Operations

✓ Federal ✓ Underground ☐ State ☐ Surface ☐ Loadout ☐ County **✓** Fee Processing ☐ Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper,

Date

Wednesday,



Inspector ID Number: 49

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Wednesday, July 28, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
- a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		V	
3.	Topsoil	V		V	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	V	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V	✓		
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070020 Inspection Type: PARTIAL

Inspection Date: Wednesday, July 28, 2010

Page 3 of 3

2. Signs and Markers

The mine identification sign is placed at thee point of public access to the permit area. The sign contains the required information.

3. Topsoil

Large loader was observed on top of the topsoil pile below the sediment pond. Contact was made with Joe Fielder, Superintendent, to arrange for the immediate removal of the loader. The loader is a rubber tired vehicle, no damage occurred to the topsoil pile.